### **USAAMRDL TECHNICAL REPORT 72-19**

OIL-STARVATION TEST PROGRAM:
EVALUATION OF VASCO-X2 STEEL SPIRAL BEVEL GEARS

FINAL REPORT

By .

J. P. Alberti A. J. Lemanski

**April 1972** 


# EUSTIS DIRECTORATE U. S. ARMY AIR MOBILITY RESEARCH AND DEVELOPMENT LABORATORY FORT EUSTIS, VIRGINIA

CONTRACT DAAJ02-72-C-0009
THE BOEING COMPANY, VERTOL DIVISION
PHILADELPHIA, PENNSYLVANIA

Approved for public release; distribution unlimited.



Reproduced by
NATIONAL TECHNICAL
INFORMATION SERVICE
US Department of Commerce
US Department of Commerce
Solve of the VA 17511



90

#### **DISCLAIMERS**

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission, to manufacture, use, or sell any patented invention that may in any way be related thereto.

AND THE PROPERTY OF THE PROPERTY OF THE PROPERTY AND THE PROPERTY AND THE PROPERTY AND THE PROPERTY OF THE PRO

Trade names cited in this report do not constitute an official endorsement or approval of the use of such commercial hardware or software.

#### DISPOSITION INSTRUCTIONS

Destroy this report when no longer needed. Do not return it to the originator.

WHITE SECTION CO
BUFF SECTION [
- <u>D</u>
***********
AVAILABILITY CODES
IL mi/o special



# DEPARTMENT OF THE ARMY U. S. ARMY AIR MOBILITY RESEARCH & DEVELOPMENT LABORATORY EUSTIS DIRECTORATE FORT EUSTIS, VIRGINIA 23604

This report was prepared by the Boeing Company, Vertol Division under the terms of Contract DAAJ02-72-C-0009.

In this effort, it was shown that the current state-of-the-art transmission gear material is not capable of operation at 100-percent power for 30 minutes in a nonlubricated environment. The results indicate that there must be some amount of lubrication or cooling to prevent the gear temperature from reaching a point where the metal begins to flow and failure occurs. Further study is indicated to develop a thermal map of the transmission which would be useful in predicting the minimum amount of lubrication or cooling that is necessary.

The technical monitors for this contract were Hr. James T. Robinson and SP4 Vick M. Crawley of the Safety and Survivability Division.

INCLASSIFIED. Security Classification DOCUMENT CONTROL DATA - R & D (Security Classification of title body of abstract and indexing amounts in must be note GRIGINATING ACTIVITY (Corporate nather) the serrall report is classified) ZAL MEPONT SECURITY CLASSIFICATION The Eoeing Company, Vertol Division Unclassified Philadelphia, Pa. #EPORT TITLE OIL-STARVATION TEST PROGRAM: EVALUATION OF VASCO-X2 STEEL SPIRAL BEVEL GEARS 4 DESCRIPTIVE NOTES (Type of report and inclusive dates) Final Report (October 1971 - December 1971) J. P. Alberti A. J. Lemanski STAC TROUSE TE. TOTAL NO OF PAGES 23 40 OF SEFE April 1972 11 90 21 SA CONTRACT OR CRANT NO A. CRICINATOR'S REPORT NUMBERS! DAAJ02-72-C-0009 USAAMRDL Technical Report 72-19 Task 1F162205AA5201 th. OTHER REPORT WILL flow other numbers that may be assigned. Boeing Document D210-10384-1 12 DISTRIBUTION STATEMENT Approved for public release; distribution unlimited. II SUPPLEMENTARY WOTES IZ SPONSORING MILITARY ACTIVITY Eustis Directorate, U.S. Army Air Mobility Research and Development Laboratory, Fort Eustis, Virginia This report presents the results of tests conducted to evaluate the performance of spiral bevol gears made from VASCO-X2 steel when they are operated without lubricating oil. Spiral bevel gears made from AISI 9310 steel and identical gears made from VASCO-X2 steel were run under load in a regenerative (four-square) test stand. The purpose of this testing was to evaluate the effect of material properties on the performance of main power gears in a nonlubricated (loss-of-oil) environment.

Details of Tecture 15 True document in a comment of marketing

T

DD FORM, 1473

UNCLASSIFIED
Security Classification

#### UNCLASSIFIED

Security Classification LINK A KET WORDS BOLE 401E POLE Oil-Starvation Test Nonlubrication Gear Testing VASCO-X2 Steel Gears Spiral Bevel Gears 1

UNCLASSIFIED

Security Classifications

Task 1F162205AA5201 Contract DAAJ02-72-C-0009 USAAM:DL Technical Report 72-19 April 1972

OIL-STARVATION TEST PROGRAM: EVALUATION OF VASCO-X2 STEEL SPIRAL BEVEL GEARS

Final Report

D210-10384-1

Ву

J. P. Alberti and A. J. Lemanski

Prepared by

The Boeing Company, Vertol Division Philadelphia, Pennsylvania

for

EUSTIS DIRECTORATE
U.S. ARMY AIR MOBILITY RESEARCH AND DEVELOPMENT LABORATORY
FORT EUSTIS, VIRGINIA

Approved for public release; distribution unlimited.

IE

#### SUMMARY

This report presents the results of tests conducted to evaluate the performance of spiral bevel gears made from VASCO-X2 steel when they are operated without lubricating oil.

Spiral bevel gears made from AISI 9310 steel and identical gears made from VASCO-X2 steel were run under load in a regenerative (four-square) test stand. The purpose of this testing was to evaluate the effect of material properties on the performance of main power gears in a nonlubricated (loss-of-oil) environment.

The general conclusions of this report are summarized as follows:

- 1. The attempt to measure gear-blank temperature by the use of temp-plate sensors was not successful, because the sensors failed under exposure to oil and very high temperatures. The use of thermal crayons for the relative measurement of gear-blank temperature, however, was successful, in that comparative temperature determinations were made between the various tests.
- The gear steel compositions used in this program did not show a significant difference in operating time (nonlubricated) at the full load level.
- 3. The increased backlash (approximately 2 to 1) resulting From the original regrind of the test specimens appeared to be insufficient to accommodate the thermal expansion experienced during the nonlubrication testing at the 100-percent and 85-percent load levels.
- 4. Test runs at the 75-percent load level resulted in light surface distress, indicating that the operational load has a significant effect on survival time after a lubrication failure.
- 5. There were insufficient test data points to establish a statistical evaluation of the test results.

I'

#### **FOREWORD**

This program was conducted during the period August 1971 through December 1971 for the Eustis Directorate, U.S. Army Air Mobility Research and Development Laboratory, Pt. Eustis, Virginia, by the Vertol Division of Boeing, under Contract DAAJ02-72-C-0009 (DA Task 1F162205AA5201).

Technical direction was provided by Mr. J. Robinson, Project Engineer, Safety and Survivability Division.

The program was conducted at the Vertol Division of the Boeing Company under the technical direction of A. J. Lemanski, Chief of the Advanced Drive System Technology Department. Principal investigators for the program were J. P. Alberti, Project Engineer, and J. C. Leeds, Assistant Project Engineer.

Acknowledgment is made to Professors W. J. Murphy and J. Curry and their staff at Villanova University for their assistance and contributions Juring the experimental test program.

Preceding page blank

#### TABLE OF CONTENTS

																								Page
Summ	ARY	•	•	•	•	-	-	•		•	•	-	-	-	-	-	•	•	•	-	-	•	-	iii
FORE	WOR!	)	-	-	-	•	•	-	-	•	-	•	-	-	-	-	•	•	-	-	-	-	-	¥
List	OF	II	LU	ST	RA	T	(0)	RS.	-	-		•	-	-	-	•	-	-	-	-	-	-		vii
List	OP	T.	\BL	£S		-	•	•	-	•	-	-	•	•	-	•	-	•	•	•	•	-	•	×
INTR	DUX	T	(ON	:			-		-	•	-	-	-	-	•	•	•	-	-	•	-	-		1
TECH	VIC/	۱L	AP	PR	O.A	ď	4		-			-				_				•				2
	Bad	ckç	ro	un	đ	-	-	_	-	-	-	•	•	-	_	-	-	•	-	•	_	-	-	2
	Sta																							3
TEST	MET.	THC	D	_	-	-		-	-		-	-				_	-			•	-		•	5
	Te:	st	Sp	ec	is	er	1	De:	5 Ī Ç	ĮΠ	-	-	-	-	-	-	_	-	-	-	-		•	5
	Ka :	:e:	ia	1	-			-		_	-	-	_		-	-	-	-	_	-	-	-		5
	Pal	ori	ca	ti	Oπ	ì	-	-	-	_	-	_	-		-	-		-		-		_		3 -
	Xe	l:a l	llu	rg	ic	ai	1	F 776	111	æ	tic	on	-	-	-	-		-		•	-	_		10
	Te:	:t	Αp	pa	ra	tı	15		-	-	_	_	_	_	-	-			-		-			10
	Te:		_																					22
	Gea	ar	Sŧ	re	SS	(	2	Ìcı	ila	et:	io	ns	•	•	-	-	•	-	-	-	-	-	•	25
TEST	RES	SUI	TS		-		-			-	-	•		•	-		•		_	•			•	30
	De:	£16	ct	io	n	76	2	t	-	_	-	-	-	-	-	-	-	-		_	-	-	•	30
	Te:																							32
	Me	tai	llu	rg	ic	a l		Ev:	11	יבני	ti	on	•	•	-	-	•	-	-	•	-	•	•	57
CONC	LUS	(OI	ß	-	•	-	-	-	-	-	-	-	-	-	-	-	•	-	•	-	-	-	•	65
RECO	eve:	ED#	TT	ON	5	-	-	-	-	-	-	-	-	-	-	-	-	-	•	-	•	-	-	67
SELE	CTEI	D I	BIB	Lī	œ	R	\P	ΗY	-	-	-	-	•	-	-	-	-	• •	-	-	-	•	•	68
በተናዋ፣	QTRO		M	i																				70

## Preceding page blank

#### LIST OF ILLUSTRATIONS

Figure		<u>Page</u>
1	Baseline Test Gears (AISI 9310 Steel) Spiral Bevel Pinion, Part No. SK23409-1	6
2	Baseline Test Gears (AISI 9310 Steel) Spiral Bevel Gear, Part No. SK23410-1	
3	VASCO-X2 Test GearsSpiral Bevel Pinion, Part No. SK23411-1	3
4	VASCO-X2 Yest GearsSpiral Bevel Gear, Part No. SK23412-1	9
5	Fabrication Sequence for Aircraft Spiral Bevel Gears	pount,
6	As-Received Condition of Baseline Test Gears	13
7	As-Received Come on of VASCO-X2 Test Gears	17
8	Boeing-Vertol Gear Research Test Stand	23
9	Deadweight Torsion Test Machine	24
Part Car	Tensile Stress in Spiral Bevel Test Gears	29
Paned Post	Contact Stress in Spiral Bevel Test Gears	29
12	Deflection Test Gear Patterns	31
- P	Vibration Signature Response of Test Gears	3-‡
14	Torque Losses in Mcnlubrication Testing	35
15	Temperature Gage Installation	36
16	Final Condition of Baseline Test Gears (AISI 9310 Steel) After Nonlubrication Testing.	=5
17	Final Condition of VASCO-X2 Steel Gears After Wonlubrication Testing	-

Figure		Page
10	Baseline Pinion Gear (AlO3) After	
	13.5 Minutes of Oil Starvation at	
	100-Percent Load	58
19	VASCO-X2 Pinion Gear (AlOl) After	
	23 Minutes of Oil Starvation at	
	100-Percent Load	59
20	Baseline and VASCO-X2 Pinion Gears	
	(AlO3 and AlO1) After Nital-Etch	
	Inspection	60
2**	Rehardening Characteristics Exhibited	
	by VASCO-X2 Pinion Gear (A101) After	
	Nital-Etch Inspection	60
22	Metallographic Profile of Tooth From	
	Baseline Pinion Gear (AlO3), Exhibiting	
	Wear and Deformation of Drive Flank	
	Carburized Case (9X)	62
23	Metallographic Profile of Tooth Prom	
	VASCO-X2 Pinion Gear (A101), Exhibiting	
	Wear and Deformation of Drive Flank	
	Carburized Case (9X)	63
24	Effective Case Depths and Hardness	
	Traverse Data of Drive Flanks at	
	the 180° Position	64

#### LIST OF TABLES

<u> Table</u>		<u>Page</u>
ĭ	Dimensional Characteristics of Reground Spiral Bevel Gears	12
II	Chemical Composition of Test Gears	21
III	Test Schedule	25
IV	Gear Specimen Data	33
V	Testing of Baseline Test Gears	39
VI	Testing of VASCO-X2 Test Gears	40
VII	Vibration Data From Nonlubrication Testing of Baseline Gears	41
VIII	Vibration Data From Nonlubrication Testing of VASCO-X2 Gears	41
IX	Thermochrom Crayon Temperatures of Saseline Test Gears at Conclusion of Nonlubrication Testing	42
х	Thermochrom Crayon Temperatures of VASCO-X2 Test Gears at Conclusion of Nonlubrication Testing	43
ХI	Observed Data From Nonlubrication Testing	44
XII	Hardness Determination	61

#### INTRODUCTION

The objective of this program was to investigate the potential of improving the survivability time of the main power spiral gears in an emergency nonlubricated environment by experimentally testing bevel gears fabricated from a carburized, high-hot-hardness, tool steel.

Considerable effort has been expended by industry in recent years in the development of failsafe rolling-elament bearing designs with the capability of emergency operation in a hostile (loss of oil) environment for a reasonable length of time. However, the practicality of extended survivability for a helicopter power transmission is also dependent on the final development of a failsafe power gear train and a supporting bearing system.

The results of several recently completed gear test programs by Boeing's Vertol Division have indicated that the high-hot-hardness characteristics of VASCO-X2 steel have the potential for improved performance in a high-load and/or high-temperature operating environment.

This report presents the results of a program conducted by Vertol to evaluate the performance in a nonlubricated environment of main power spiral bevel gears manufactured from the currently used gear steel, AISI 9310 (AMS6265), and from VASCO-X2 steel.

#### TECHNICAL APPROACH

#### BACKGROUND

Previous development efforts to improve power transmission gear materials have not considered high-hot-hardness characteristics and emergency operation under no-cil conditions. need for improved gear materials has usually been based on the desire for higher load-carrying capacity without increases in This requirement has resulted in an effort to gear size. improve core strength and hardenability. In the past, gear steel development has been essentially limited to the addition of varying quantities of carbon, chromium, nickel, and molybdenum as alloying elements. However, the choice of alloying elements is dictated by the effects of the elements on the uniformity of carburizing and the compatibility of case-core heat treatment. The present standard gear material of the aerospace industry is AISI 9310 steel. This material incorporates these alloying elements to a degree and generally provides a good combination of properties. The current aerospace gear steels are heat-treated by conventional guench and tempering methods.

In the past, helicopter main power gear design was based primarily on bending fatigue strength, usually resulting in the selection of coarse-pitch tooth designs. This approach has often limited the surface durability in favor of bending strength and produced early surface failures (scuffing, pitting, etc.). Scoring (scuffing) is a phenomenon which occurs when the film of lubricating oil breaks down and permits metal-to-metal contact of the gear tooth surfaces. This metal-to-metal contact results in the development of high frictional heat which, in turn, tempers the gear tooth surfaces. Continued operation under these conditions will ultimately produce metal flow, which alters the tooth profiles and destroys the load-carrying capacity of the gear set.

Advanced gear materials now in the process of Jevelopment indicate the capability to resist plastic flow at elevated temperatures. Past experience with helicopter transmission operation during emergency conditions (loss of lubrication) indicates that the resulting high-temperature environment requires a gear material with the capability of resisting excessive erosion and softening of to carburized case, and still maintain sufficient hardness. The candidate materials

under development that display this potential are secondary hardening steels, similar to those used in tool fabrication. These materials develop their maximum hardness by tempering between 950°F and 1100°F. Thermal exposure of these materials to temperatures below the tempering range will not significantly alter room temperature hardness, as compared to conventional carburizing steels that will display case softening at temperatures as low as 350°F.

#### STATEMENT OF PROBLEM

The main gearboxes of current helicopter power transfer systems are the heart of the propulsion system, charged with tremendous responsibility for safe flight of the entire aircraft. There are few other types of vehicles which place such stringent demands on power gears and bearings for reliability and performance. Combat operation of helicopters in Southeast Asia has shown that the helicopter oil-cooling system is susceptible to combat damage due to the remote location of coolers and blowers with their extensive plumbing systems.

This service experience (corroborated by tests) indicates the dependence of the helicopter transmission system on a continuous flow of lubricating oil to the main power gears and bearings. On the occasions when the oil supply has been interrupted, the transmission sympleal times are of extremely short duration, particularly in the area of high input speed.

Interruption of this cil flow from any cause would normally dictate an immediate power-off descent and landing. Under certain circumstances, such as over open water, over enemy terrain, or in the dark, this would be a hazardous operation. It is therefore obvious that a need exists for prolonging the safe operation of the drive system for approximately 30 minutes after the loss of cil.

Main power gearing in current helicopter transmissions is limited in load-carrying capacity by the fact that current gear materials are subject to early surface failures in the form of scuffing, pitting, or spalling. The bending scrength and flexural resistance of these materials have not typically imposed significant limitations on performance. The primary concern of the transmission gear design engineer is to provide adequate tooth strength in order to preclude the possibility of catastrophic failure; therefore, gear materials have been selected on the basis of beam strength requirements. The current family of aerospace carburizing gear steels has very limited hot-hardness capability. Experience with these steels has not demonstrated a significant effect in resisting the scuffing or pitting hazard. The implication is that these steels will not provide adequate survival time under conditions of total oil loss, whereas a not-hardness steel could provide for an adequate failsafe operating time period.

The contractor has conducted several programs under Government and company funding to evaluate candidate advanced year materials. One material is identified by nomenclature as VASCO-X2 steel. Several formulations of this high-hot-hardness tool steel have been investigated. Some formulations differed in chemical composition; the percentages of both carbon and tungsten were varied. The test data from these programs revealed that certain formulations of VASCO-X2 steel permitted a substantial increase in tooth loading without resulting in a surface or bending tooth failure.

#### TEST METHOD

#### TEST SPECIMEN DESIGN

Spiral bevel gears from a previous Government-sponsored test program (Contract DAAJ01-70-C-0453(1G), AVSCOM) were used as the test specimens.

Eight each spiral bevel pinions and gears of AISI 9310 AMS6265 steel, part numbers SK23409-1 and SK23410-1, were reground to remove the tooth surface finish resulting from the previous program for use as the baseline test gears. Eight each spiral bevel pinions and gears of VASCO-X2 consumable-electrode vacuum-melt (CVM) steel, part numbers SK23411-1 and SK23412-1, were reground to remove the tooth surface finish from the previous program and were used as the test gears for comparison with the baseline gears. All the test specimens were designed to the following general specifications:

Diametral Fitch 5.833 (nondimensional)

Pitch Diameter Pinion 6.00 inches, gear 7.372 inches

Face Width 1.426 inches

Number of Teeth Pinion 35, gear 43

Pressure Angle 22 degrees 36 minutes

Spiral Angle 26 degrees

The detail specifications for the test gears are shown in the engineering drawings, figures 1 through 4.

#### MATERIAL

である。 では、100mmには、100m

The baseline spiral bevel test pinions (SK23409-1) and test gears (SK23410-1) were made of AISI 9310 (AMS6265) consumable-electrode vacuum-melt steel. This material is currently used for most helicopter main power gears. The remaining test spiral bevel pinions (SK23411-1) and test gears (SK23412-1) were of VASCO-X2 (0.15 carbon) consumable-electrode vacuum-melt steel. This steel had shown promise of increased








Figure 1. Baseline Test Gears (AISI 9310 Steel) -- Spiral Bevel Pinion, Part No. SK23409-1.









NOTES:

- L JUL DIAMETERS ON A COMMON CENTER LINE TO BE CONCENTRIC TO EACH OTHER WITHIN COSTIR UNLESS OTHERWISE NOTED & MAXIMUM SURFACE ROUGHNESS MY EXCEPT AS NOTED. 3 FINISH ON GEAR TEETH. MYMIN OF MAX ON FLANKS SEY ON FILLETS.

- 4 BREAK ALL SHARP EDGES NOT SPECIFIED TO A RAD US OR CHAMPER OF JOID TO DED

THEAT TREATMENT:

- A. CARBURIZE ENCLOSED AREAS PER BOEING PROCESS SPEC WS1202 AREA'A' B. CARBURIZED CASE HARDNESS ROCKWELL C C. EFFECTIVE CASE DEPTH AFTER GRINDING ---
- 080 ,050 38 48 144,000 194,000 D. CORE HARDNESS ROCKWELL C E. CORE STRENGTH PSI (REF) -
- F. DRAW AT 300°F-365°F FOR FOUR HOURS AFTER FINAL GRIND (4) FLUORESCENT MAGNETIC PARTICLE INSPECTION PER BOEING PROCESS SPECIFICATION BAC 542C, CLASS A.
- MATERIAL: 200+ 8-00 DIA. FOR GING STEEL AMS GEGG; AISI 9310 CVM BAS 76 HRD & TEMP
- S RELATIVE AZIMUTH POSITION OF GRAR TRETH AND HOURS OPTIONAL UNLESS SPECIFIED 9. HITAL ETCH INSPECTION FOR BORING PROCESS SPECIFICATION BACS436, DO NOT GRIT BLAST
- D MARK PART AND SERIAL NUMBER HERE VIEWD ETCH PER ROBING SPECIFICATION SACSSOT TYPE'VE' DO NOT IMPRESSION STAMP. CHARACTERS MG HIGM.
- II. BILLET OR BAR SHALL HAVE A MINIMUM MECHANICAL REDUCTION OF \$ 101 PROM THE INGOT

Figure 2. Baseline Test Gears (AISI 9310 Steel) --Spiral Bevel Gear, Part No. SK23410-1.








Figure 3. VASCO-X2 Test Gears--Spiral Bevel Pinion, Part No. SK23411-1.









#### NOTES!

- LALL DIAMETERS ON A COMMON CENTER LINE TO BE CONCENTRIC TO EACH OTHER WITHIN OOS TIR UNLESS OTHERWISE NOTED E. MAXIMUM SURFACE ROUGHNESS BY EXCEPT AS NOTED 3 FINISH ON GEAR TEXTH: SYMIN BY MAX ON FLANCE BY ON FILLETS.
- 4. BREAK ALL SHARP EDGES NOT SPECIFIED TO A RADIUS OR CHAMPER
- 0# .010 TO .010
- E. RELATIVE AZIMUTH POSITION OF SEAR TEETH AMB MILES OPTIONAL UNLESS SPECIFIED.

  6. WILL ETCH MISPECTION PER BORMS PROCESS SPECIFICATION: BAC 8436, DO NOT GRIT BLAST.

  "DAMAR PART AND SERNAL MINISTER MERE, VISING ETCH PER BORMS PROCESS SPECIFICATION

  BAC 5307 TYPE VEL. DO NOT MINISTESSION STAMP CHARACTER. PHE HIGH.
- & BILLET OF BAR SHALL HAVE A MINIMUM MECHANICAL REDUCTION OF 3 TO 1 FROM THE INGOT.
- 9 FLUORESCENT MAGNETIC PARTICLE INSPECTION PER BOEING PROCESS SPECIFICATION BAC 5424 CLASS A.
- THE PUNCHASE MODIFIED WISCO-XE STEEL, CONSUMABLE ELECTRODE WICCOM MELT, FROM: VARADRUM ALLOYS STEEL COMPANY "MISCO" LATRODE, PENNSYLVANIA.

CARBON .12-.6 SULPHUR .018 MAL MOLYBDENUM 1.90-180 SULCON .80-100 PHOSPHORUS .018 MAIR WARADHUM .40-.50 MANGANESE .20-.40 CHROMBM 4.78-9.19 TUNGSTEN 1.20-180 SHICON

VASCO-X2 Test Gears--Spiral Bevel Gear, Figure 4. Part No. SK23412-1.

potential for surface load capacity in previous test programs, and it represented the major test variable in this test program.

#### PABRICATION

The test gears were manufactured earlier by Boeing-Vertol for AVSCOM under Contract DAAJ01-70-C-0453(1G). A representative sequence of manufacturing operations for the fabrication of typical aircraft spiral bevel gears is shown in Figure 5.

Eight gear sets of each type of steel were reground to remove the tooth surfaces resulting from the previous test program. The physical dimensions resulting from the regrinding process are shown in Table I. Figures 6 and 7 show the as-received condition of the gears prior to testing.

#### METALLURGICAL EVALUATION

Destructive metallurgical examinations were not conducted prior to implementing the test program. Table II presents the material evaluation conducted on the previously completed Contract, which is representative of the test gears used for this program.

#### TEST APPARATUS

All gear test specimens for this program were evaluated on the Boeing-Vertol gear research test stand located at Villanova University. This test apparatus was specifically designed for research and development programs for spur, helical, and bevel gears. The design incorporates provisions for center distance option, variable speed, and control of oil temperature and oil flow. The system is a regenerative (four-square) design using one gearbox as the slave unit and one gearbox as the test unit. Gear scantings were designed to be rigid and stable under all loading conditions with through-bored housings for maximum accuracy. All gear shafting is supported on ball and roller bearings lubricated by individual oil jets.

For this test, cil slingers were fabricated and installed on the inside of the gear case on the test spiral bevel pinion and gear to prevent oil mist from the bearing lubrication from influencing the nonlubricated performance of the test gears. A remote-controlled solenoid valve was installed to close the





Figure 5. Fabrication Sequence for Aircraft Spiral Bevel Gears.

THE I. PRESIDEN CARACTERISTICS OF REMARD STITL RETEL CLAS Pounting Assemble: Tooth \$22002 i Distance Per Side Serial 7451 Finish tacliss) Tolerwee Set. Sinnie: Buthle : (inc) (rms) (خهدنا) المحدث ALSE 1010 (JESA245) Statel 572 )494-1 A102 0.001 23-25 9.014 **\$.**\$ 572 H 10-1 23-24 AIW **\$.5** 532)1404-1 A16) 0.001 27-78 0.014 **\$.**\$ 532 1415-1 A161 23-24 4.4 532 345/9-1 A164 0.0064 23-25 G.0175 **4 4** 552 |410-1 Alé4 22-23 0.0 530 2407-1 A105 0.004 24-25 0.013 €\_€ 5323416-1 礼的 23-24 2.0 5523499-1 A105 0.01) 0.002 23-25 0\_0 587 J410-1 A144 22-23 0.0 532 1497-1 **1107** 0.50% 24-25 0.014 **6. 6** SX23410-1 A:#7 23-24 0.0 A)48 SX2 MOY-1 0.00) 24-25 ē. ⊕14 0.0 55Q H10-1 AICP 24 0.0 SEZ MOY-1 AID'S 0\_CO) 24-25 6.0 9,014 SX23410-1 A107 -0.01¢ 23-24 VASCO-II Steel 582 1411 -1 Aloi 9.051 25-24 0.014 6.0 20 HU-1 0.004 AIO 25-26 0.0 307 H11-1 A IOT 0.00 24-25 0.011 0.0 503 H 12-L 24-25 101 2.001 0.0 SEQ HII-I Alot 0.005 24-25 0.0:5 0.0 552 1412-1 2104 0.00) 25-24 5.0 SQ MII-I **是10%** 0.001 24 -25 ė.01-9.0 5X7 M12-1 A!GT 0.003 24-25 0.3 SEPMII-I 2139 0.351 14-15 ÷\_3[4 **100 科17-1** 4137 0.*4*F) 7-**4.**4 1-114(認 2113 a dell' 24-25 **∌.**€14 6.0 SCHO-I Alle a (##) 7 E 0.0 SCHU-1 AIII 9.05 25-76 0.015 9\_9 **30 MI2-1** AIIZ 0.00) 74-25 6.0 587 1411-1 1112 d (00 t 35-76 0.014 6.0 SET 1412-1 AMI d.cou 24-25 a :



Pinion Number A102



Gear Number Al02



Pinion Number Al03



Gear Number A103

Pigure 6. As-Received Condition of Baseline Test Gears (Sheet 1 of 2).






ION NUMBER ATOS



r Number Al03




Pinion Number Al05




Gear Number Al05








Pinion Number A107



Gear Number A107



Pinion Number A108




Gear Number Al08



VASCO-X2 GEAR: SET 1


VASCO-X2 GEAR SET



Pinion Number A101



Gear Number A102



Pinion Number Alo



Gear Number A106

Figure 7. As-Received Condition of VASCO-X2 Test Gears (Sheet 1 of 2).




Preceding page blank

17

SCO-X2 GEAR SET 2

VASCO-X2 GEAR SET 3




inion Number Al04 '



Gear Number Al05




Pinion Number Al06



Gear Number Al07

VASCO-X2 GEAR SET 4


VASCO-X2 GEAR



Pinion Number Al09



Pinion Number



Gear Number Al09



Gear Number


Figure 7 - Continued (Sheet 2 of 2).



Preceding page blank




Number Allo



Number Allo



Pinion Number All2



Gear Number All3



TABLE	II. CHEMICAL	COMPOSITIO	ON OF TEST GEAF	RS .
		Percent by	Weight	
Element	AISI 9310 (A Specified	AMS6265) Actual	VASCO-X2 Specified	
Carbon	0.07 to 0.13	0.11	0.12 to 0.16	0.17
Manganese	0.40 to 0.70	0.75	0.20 to 0.40	0.29
Silicon	0.20 to 0.35	0.37	0.80 to 1.00	1.00
Chromium	1.00 to 1.40	1.33	4.75 to 5.25	5.10
Molybdenum	0.08 to 0.18	0.09	1.30 to 1.50	1.50
Vanadium	-	-	0.40 to 0.50	0.52
Tungsten	-	-	1.20 to 1.50	1.38
Nickel	3.00 to 3.50	3.25	-	~
Case hardness	-	61 to 62	-	62 to 63
Core hardness	-	44	-	36
Grain size	••	-	<del>-</del>	8

## Preceding page blank

test gear mesh oil jet for the nonlubricated portion of the test. Figure 8 shows the configuration used for this program.

#### TESTING TECHNIQUE

The primary test variables were shaft torque and oil inlet temperature. Gear tooth load was a function of shaft torque, which was applied through a lever system at the beginning of each test run. Torque levels were observed on a Strainsert SR2 instrument at the beginning and end of each test run. Deviation from the initial target torque was controlled within ±5 percent at test startup.

The torquemeter was calibrated before and after the test program on a Riehle deadweight torsion test machine (Figure 9). Recalibration curves agreed with the initial curves within 2 percent. Test time (cycles) was determined by a log record of running time and an elapsed-time meter at the test stand console. Power was supplied by a 100-hp electric motor driving the input shaft through a toothed-belt arrangement, maintaining the input pinion speed at 3,410 rpm.

Inlet oil temperature for the test gearbox was controlled at 190+5°F, with an oil pressure of 55+5 psi. The oil used for lubrication of the test gears was MII-7808-G. Test runs were begun after the outlet oil temperature stabilized.

Before the test runs were begun, deflection tests were conducted by mounting the test gears in the test box, applying specified loads, and rotating the gear set through mesh by hand, to evaluate the contact pattern (load distribution).

The test procedure used for all gears in this program was the same. Each gear set (spiral bevel pinion and gear) was installed in the test gearbox, with the specified backlash at the specified mounting distance. The lubricating oil was heated to 190±5°F and then circulated by the pumps. Torque was applied after stabilization of the oil outlet temperature; the test run began at this point. The test schedule given in Table III was performed on both the AISI 9310 steel and the VASCO-X2 steel spiral bevel gears as follows:





Figure 8. Boeing-Vertol Gear Research Ters Stand.



intere of beadweight Porsion Test Machine.

	TA	BLE III. TE	ST SCHEDULE	
		Fer	cent Load	
		With Lubricat	ion	Nonlubrication
Set	1/2 Hr Run-In	1/2 Hr Run-In	l Hr Run-In	30 Min (Max)
1	50	50	100	100
2	50	50	100	100
3	50	50	85	<b>85</b>
4	50	50	85	85
5 6	50 50	50 50	70 70	70 70 .

The run-in tests were used to determine temperature stabilization, wearing-in of the tooth profiles, and general system checkout. At the conclusion of these runs, the gear tooth surfaces were visually inspected to evaluate the surface co.dition.

#### GEAR STRESS CALCULATIONS

To maintain a consistent and accurate rating practice, most of the major aircraft companies and engine manufacturers use the American Gear Manufacturer's standards for strength rating. Although the AGMA gear rating formulas for strength and durability provide for the use of modifying factors to account for misalignment, dynamic conditions, overload conditions, size effect, etc., specific values for these factors as applicable to helicopter transmission gears do not exist. This requires a comparison of gear stresses with operational and test experience gained in previous design efforts.

The methods and/or experience currently being used for forecasting stress allowables and gear life in the design of helicopter transmission gearing cannot be applied directly for test specimens operating in gear research type test stands. The alignment, rigidity, dynamics, etc., of an R&D test stand act to improve the load capacity of the actual test specimens. Past experience with the Boeing-Vertol R&D test stand used for this program has indicated an increased load capacity for test gears (depending on gear type) in the range of 1.5 to 3.0

times the design allowables established for aircraft power gears. Consequently, it is not practical to establish a basic load level for test gears in the design stage for R&D operation in a test stand environment without relating these loads to standard design practice. Therefore, it must be expected that baseline configuration test gears will operate in an R&D test stand at stress levels above the 100-percent load level, which has been established for operation in an aircraft transmission, without failure.

The 100-percent design load for the test gear configurations utilized in this test program was established and defined as that load (10,000 inch-pounds pinion torque) which results in a bending stress of 31,400 pounds per square inch and a Hertz stress of 211,000 pounds per square inch, which is commensurate with current levels established for helicopter main power spiral bevel gears.

The test gear stress levels presented in this report were calculated by an existing Boeing-Vertol computer program based on the Gleason method and the following AGMA standards:

.216.01 - Surface Durability (Pitting) Formulas for Spiral Bevel Gear Teeth

223.01 - Rating the Strength of Spiral Bevel Gear Teeth

AGMA Standard 223.01 rates the bending strength of spiral bevel gear teeth as follows:

$$St = \frac{Wt \times Ko}{Kv} \times \frac{Pd}{P} \times \frac{Ks \times Km}{J}.$$

Wt = transmitted tangential load in pounds

Ko = overload factor

Rv = dynamic factor

Pd = diametral pitch at large end of tooth

P = face width in inches

Ks = size factor

Km = load distribution factor

J ≈ geometry factor

For the test specimens in this program, assume that

Ko, Kv = 1.0

F = 1.426

Pd = 5.833

J = 0.3067 (calculated by computer program)

Ks = 0.6416

Km = 1.1

Therefore, the test specimen tensile stress is

St = 
$$\frac{\text{Wt x 1.0}}{1.0}$$
 x  $\frac{5.333}{1.426}$  x  $\frac{0.6416 \text{ x 1.1}}{0.3067}$ 

St = 9.421 Wt (see Figure 10)

AGMA Standard 216.01 rates the contact stress of spiral bevel gears as follows:

$$Sc = Cp \sqrt{\frac{\text{Wt x Co}}{Cv} \times \frac{Cs}{dF} \times \frac{Cm \times Cf}{I}}$$

Cp = elastic coefficient (2,800 for steel)

Wt = transmitted tangential load at operating pitch
 diameter in pounds

Co = overload factor

Cv = dynamic factor

d = pinion operating pitch diameter in inches

F = face width in inches

Cs = size factor

Cm = load distribution factor

I = geometry factor

Cf = surface condition factor

For the test specimens used in this program, assume that

Co, Cv, Cs, 
$$Cf = 1.0$$

$$F \approx 1.426$$

$$Cm = 1.1$$

$$d = 6.00$$

Then,

Sc = 2800 
$$\sqrt{\frac{\text{Wt x 1.0}}{1.0} \times \frac{1.0}{6.000 \times 1.426} \times \frac{1.1 \times 1.0}{0.0767}}$$

Sc = 
$$2800 \sqrt{\frac{1.1 \text{ Wt}}{0.6562}}$$
 (see Figure 11)




Figure 10. Tensile Stress in Spiral Bevel Test Gears.

ANNOTED SOLVED TO A STATE OF THE STATE OF TH




Figure 11. Contact Stress in Spiral Bevel Test Gears.

## TEST RESULTS

# DEFLECTION TEST

Analytical evaluation of the load-carrying capacity of bevel gears involves assumptions regarding the nature of the tooth bearing for the specific gear mountings under load. Unless these assumptions are relatively accurate, actual stresses may vary considerably from the calculated values, resulting in a possible life reduction.

During manufacture of bevel gears, the desired tooth contact pattern is established from observation of the pattern obtained under light load in a gear tooth pattern checker. It is possible by selection of grinding wheel diameters and grinding machine settings to vary the length, width, and position of a tooth bearing.

With gear mountings that are rigid, the behavior of the tooth bearing under load is usually more predictable. Consequently, it is usually possible to develop tooth bearing patterns which are based on previous experience. However, in the case of aircraft applications, the mounting designs are markedly different, in that rigidity is sacrificed in favor of weight Therefore, it is seldom possible to accurately reduction. predict, during the design stage, the type of tooth bearing required at no load in a tooth pattern checker in order to obtain the desired bearing pattern in the final gear mountings. A study of the mounting design and operating conditions together with a judgement based on experience must be used to establish the initial tooth bearing. From this point, the development of the final tooth bearing is accomplished by actual trial of the gears in their final mountings.

Tooth bearing pattern evaluations were made at the 50-percent and 100-percent load levels on the first set of baseline test gears. This was accomplished by applying rouge to the teeth of the pinion member, in several sectors, and rotating the gear set through mesh by hand. Results of this deflection test were considered to be satisfactory and are shown in Figure 12.

BOEING VERTOR "

Date 10/12/71

# RECORD OF DEPLECTION TEST GEAR PAPTERN

PART NO		_RSK23410-1	SFRIAL NO. GEAR A162 PILION A102
NO. TYE		ora 43 Prixton 35	HAND OF SPIRIL GRAR R/H PINION L/H
SUMMARY	m.	145.65€-1	BACKLASH TOTAL .012014
PERCEN LOAD	1	GEAR PATTERN	PINION PATTERN
0	D		
	D		
50	1 A Distance 1-20 Miles and 1-20 Mil		
	D		
100	-   ];		
;	, D		

Figure 12. Deflection Test Gear Patterns. .

## TEST DATA

The objective of this experimental test program was to evaluate the material effect on performance of main power spiral bevel gears operating in a nonlubricated environment.

A summary of the test results is shown in Table IV, which contains the pertinent information obtained during the test phase, including part numbers, serial numbers, gear type, load levels, and test time.

#### Load Schedule


The basic 100-percent design load level for all of the test gears was established as 3333 pounds tangential load (10,000 inch-pounds pinion torque), resulting in a bending stress of 31,400 pounds per square inch and a contact stress of 211,000 pounds per square inch as calculated by the American Gear Manufacturers Association standards.

Each gear set was subjected to two consecutive runs at the 50-percent load level with lubrication, followed by a one-hour run at the specified load level with lubrication. At that time, the lubricating cil was shut off by a remote-controlled solenoid, and the test was continued for one-half hour maximum, with no lubrication to the test gear mesh. During each test run vibration surveillance was provided by visual observation of the oscilloscope traces (see Figure 13). Torque readings were taken immediately after the conclusion of the nonlubrication testing to determine the degree of torque loss. Figure 14 presents a summary of the torque losses for all nonlubrication testing.


# Temperature Instrumentation

Temperature-sensitive gages were applied to the heel end of the spiral bevel test pinions (see Figure 15) in an attempt to record the blank temperature during the test runs, particularly in the nonlubricated testing. These gages were heat sensors, on a plate, with self-adhesive and hermetically sealed heat-sensitive elements which change chemical structure at given calibrated temperatures. Two individual plates were used on each test pinion in the following ranges: 230°F, 240°F, 250°F, 260°F and 350°F, 400°F, 450°F, 500°F. Prior to installation on the gears, several bench tests were conducted


	TABLE IV.	GEAR SPECI	MEN DATA	
Run Number/ Material	Load (percent)	Pinion (s/n)	Gear (s/n)	Nonlubr. Run Time (minutes)
1/9310	100	A102	A102	25
2/9310	100	A103	A103	13.5
3/VASCO	100	A101	A102	25
4/VASCO	106	A104	A106	19
5/9310	85	A106	A105	30
6/VASCO	85	A106	A107	17
7/9310	85	A106	A106	30
8/VASCC	85	A109	A109	30
9/9310	75	A107	A107	30
10/VASCO	75	A110	A110	30
11/9310	75	A108	A108	30
12/VASCO	75	A112	A113	30




Minutes Benjabilication



30 Minutes Neutubrigation



O Minutes Nonlubrication



I Minute Nonlubrication

Vibration Signature Response of Test Gears. Figure 13.




Figure 14. Torque Losses in Nonlubrication Testing.




Figure 15. Temperature Gage Installation.

with 400°F MIL-L-7808 lubricating oil to select a protective coating for the temperature gages. Results of this experiment indicated that M-BOND 610 gage cement would provide the most protection for the gages against the lubricating oil. However, during the actual testing, the gages either turned completely black or were removed during nonlubrication testing.

Temperature-sensitive crayons were used as a backup method for recording gear-blank temperatures at the end of the nonlubrication tests. The crayons were applied directly to the gear teeth through the inspection cover at the conclusion of the nonlubrication testing, and the results were recorded. During the second baseline run, verification of the temperature evaluation of the crayons was provided by using an external pyrometer, which indicated approximately the same temperature as the crayons.

# Gear Testing

Twelve sets of spiral bevel gears were run on the test stand: six sets of baseline test gears (AISI 9310 steel) and six sets of VASCO-X2 test gears.

<u>Baseline Test Gears</u> - Each set consists of a pinion, part number SK23410-1. and a gear, part number SK23410-1. All components were numbered serially:

Set No. 1 is pinion AlO2 with gear AlO2

Set No. 2 is pinion AlO3 with gear AlO3

Set No. 3 is pinion AlO5 with gear AlO5

Set No. 4 is pinion AlO6 with gear AlO6

Set No. 5 is pinion Al07 with gear Al07

Set No. 6 is pinion AlO8 with gear AlO8

<u>VASCO-X2 Test Gears</u> - Each set consists of a pinior, part number SK23411-1, and a gear, part number SK23412-1. All components were numbered serially:

Set No. 1 is pinion AlOl with gear AlO2

Set No. 2 is pir.ion AlO4 with gear AlO6

Set No. 3 is pinion A106 with gear A107

Set No. 4 is pinion Al09 with gear Al09

Set No. 5 is pinion AllO with gear AllO

Set No. 6 is pinion All2 with gear All3

Testing was conducted in accordance with the load schedule. The test procedure and the principal results are given in Table V for the baseline gears and in Table VI for the VASCO-X2 gears.

Run-in testing was done at the 50-percent load level. Visual inspections of the tooth surfaces were conducted at the conclusion of each run-in test. Results of these inspections indicated no evidence of surface distress or damage. The load runs were conducted at increased loads: 75 to 100 percent (see Tables V and VI).

The nonlubrication testing was conducted by shutting off the oil supply to the gear mesh in the middle of a load run and continuing the load run until there was a significant growth in the vibration signature. A rapid increase in vibration (to a level more than two and a half times the level noted at the beginning of nonlubrication testing) constituted a failure, and the test run was ended. This criterion was developed as a result of testing the first baseline gear set, and it was used for all the remaining tests. Vibration data are given in Tables VII and VIII. Thermochrom crayon temperatures are given in Tables IX and X.

Pinion-blank temperatures and torque losses (given in Table XI) were checked after each test within minutes of shutdown. Torque losses are attributed to the damage and subsequent wearing away of material from the contacting gear tooth profiles.

At the conclusion of the nonlubrication testing, the tooth surfaces of both members (pinion and gear) were given a visual inspection. Photographs showing the final condition of the tooth surfaces are given in Figures 16 and 17.

Baseline Gear Set Number 1 - At the end of the run-in tests, the temperature gages were not exposed. After 20 minutes of non-lubrication testing, the vibration signal grew to approximately four times the signal seen at the start of the test run, and the test was ended. The rapid growth in vibration signal occurred in a very short time (seconds), indicating the need for constant visual surveillance of the oscilloscope. Visual inspection of the gear tooth surfaces at the end of nonlubrication testing revealed severe scoring and metal flow, heat discoloration, and pitchline pitting, but no cracks. Metal was transferred from the tips of the teeth on the drive side and

######################################	23	Encloses (FF)  20 with 12 20 with 12 20 with 12 20 with 12 20 20 20 20 20 20 20 20 20 20 20 20 20	Tiperation Trace! (cm)	C1. Prefuger (pt1)  55 56 56 56 58 58 58 58 55 55 55 55	15/000 (*1) 190 (4) 190 (4) 19	**************************************	Cil Press_rel (psi) S' 55 55 55 61 52 58 57 58 57 55 55 55		Titorico Tracer (cm)
### 15: \$5-703  ### ### #### #######################	5-2 5-5 5-5 5-5 5-5 5-5 5-5 5-5 5-5 5-6 5-7 5-6 5-7 5-7 5-7 5-7 5-7 5-7 5-7 5-7 5-7 5-7	20 ATTS 11 199-197 199-199 190-192 190-192 191-192 191-195 191	.40 .40 .40 .40 .40 .40 .40 .40 .40 .40	55 14 14 14 14 15 15 15 15 15 15 15 15 15	199 (A) 190 (A	.9 .9 .9 .8 .8 .8 .9 .5 .4 .5	\$2 55 55 55 55 55 55 55 55 55 55 55 55 55	(*1)  195 196 197 197 198 196 199 1966 199 1966 199 1966 296 1966 296 1966 296 1966 296 1966 296 1966 296 1966 296 1966 2966 1	海南南岛 李寿彦帝 第名 7 7 7
## 13 29 30 20 20 30 30 30 30 30 30 30 30 30 30 30 30 30	5-5 5-5 5-5 5-5 5-5 5-5 1-5 5-5 5-5 5-5	199-187 199-193 199-193 199-193 199-193 199-193 199-193 199-193 199-193 198-19	. 10 . 10 . 10 . 10 . 10 . 10 . 10 . 10	54 54 54 54 55 55 55 55 55 55 55 55 55	192 149 192 149 193 149 185 149 185 149 185 149 195 195 195 195 195 195 195 295 185 295 185 295 195 295 195 295 195 295	.9 .9 .9 .8 .8 .8 .9 .5 .4 .5	\$1 \$5 \$5 \$1 \$2 \$2 \$2 \$3 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5	197 193 198 197 199 198 199 198 199 198 198 298 298 298 298 298 198 298 198 298 198 298 198 298 198 298	· · · · · · · · · · · · · · · · · · ·
13 24 24 24 24 24 24 24 24 24 24 24 24 24	55 45 52 2350000 45 45 45 45 55 55 55 55 55 55 55 55 55	190 191 190 192 190 192 10 190 197 196 197 196 195 196 195 196 195 196 196 197 199 197 199 197 199 197 199 197 199 197 199	.40 .40 .40 .40 .40 .40 .40 .40 .40 .40	54 54 54 54 55 55 55 55 55 55 55 55 55	192 149 192 149 193 149 185 149 185 149 185 149 195 195 195 195 195 195 195 295 185 295 185 295 195 295 195 295 195 295	.9 .9 .9 .8 .8 .8 .9 .5 .4 .5	\$1 \$5 \$5 \$1 \$2 \$2 \$2 \$3 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5	197 193 198 197 199 198 199 198 199 198 198 298 298 298 298 298 198 298 198 298 198 298 198 298 198 298	· · · · · · · · · · · · · · · · · · ·
20 pm short down in his 20 to 10 to	45 55 64 65 65 65 65 65 65 65 65 65 65 65 65 65	190-190 191 191 191 191 190-190 191 191 191 195 191 191 195 191 191 195 191 191 191 191 191 191 191 191 191	. 20 . 20 . 20 . 20 . 20 . 20 . 20 . 20	14 14 14 15 15 15 15 15 15 15 15 15 15 15	192 189 192/192 185 181 180 190 190 190 190 190 190 190 190 190 19	.9 .9 .8 .8 .9 .9 .4 .5	55 55 61 52 58 57 55 55 55 55 55 55	196-197 195-196 197-196 197-196 197-196 197-196 296-297 296-295 197-295 197-295 197-295	· · · · · · · · · · · · · · · · · · ·
Shut down in his to the his to th	130-1 151 155 155 155 130-1 130-1 130-1 155 155 155 155 155 155 155 155 155 1	THE 187 199 199 199 199 199 199 199 199 199 19	. Cristal of the control of the cont	146 146 15 15 15 15 15 15 15 15 15 15 15 15 15	195 197 195 197 195 199 195 195 195 295 195 295 197 295 197 295 197 295 197 297 197 297	.9 .9 .8 .8 .9 .9 .5 .4 .5	55 61 52 58 57 55 55 55 55 55	195.798 192.796 195.796 293.296 293.296 293.296 293.795 195.795 196.795 196.795	· · · · · · · · · · · · · · · · · · ·
10 20 10 20 20 20 20 20 20 20 20 20 20 20 20 20	44 44 1 44 1 44 4 44 4 44 4 44 4 44 4	196 187 196 195 196 195 196 195 18 196 18 198 186 196 187 198 187 199 187 199 187 199 187 198	. 109 . 109	100 145 15 15 15 15 15 15 15 15 15 15 15 15 15	199 199 199 199 199 299 299 299 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299	.9 .8 .9 .9 .4 .4 .4	\$2 \$4 \$7 \$5 \$5 \$5 \$5 \$5 \$5 \$5	292/2017 10 200 200 200 200 200 200 195 201 195 201 195 201 195 201	· · · · · · · · · · · · · · · · · · ·
20 % % % % % % % % % % % % % % % % % % %	55 1 2200-2 5 5 1 5 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2	196, 196 196 196 196 196 196 196 196 196 196	. 109 . 109	100 145 15 15 15 15 15 15 15 15 15 15 15 15 15	199 199 199 199 199 299 299 299 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299 199 299	.9 .8 .9 .9 .4 .4 .4	\$2 \$4 \$7 \$5 \$5 \$5 \$5 \$5 \$5 \$5	292/2017 10 200 200 200 200 200 200 195 201 195 201 195 201 195 201	· · · · · · · · · · · · · · · · · · ·
10 40 5000 40 1000 100 100 100 100 100 100 100	11 11 12 12 12 12 12 12 12 12 12 12 12 1	196 195 196 195 17 18 198 186 198 186 195 187 199 187 199 187 198 187 298 185 298	. 19 . 20 . 20 . 24 . 44 . 45 . 42 . 44 . 44 . 44	148 15 15 15 15 15 15 15 15 15 15 15	-755-C507 St755-C507 St7	.8 .8 .9 .9 .5 .4 .4 .5	報 57 55 55 55 55 55 55	203 203 203 203 203 203 203 203 203 203 203 203 203 203 203 203 203 203	· 唐 · · · · · · · · · · · · · · · · · ·
#### #### ############################	230-1 230-1 25-1 25-1 25-1 25-1 25-1 25-1 25-1 25	75 7537 757 757 757 757 757 757 757 757	.20 .20 .20 .20 .20 .20 .20 .20 .20 .20	19 15 15 15 15 15 15 15 15 15 15	-255-C507 (a) -2	.8 .9 .9 .4 .4 .4 .4 .4	\$7 \$5 \$5 \$5 \$5 \$5 \$5 \$5 \$5	200 7-10 200 7-10 200 7-10 200 7-10 200 7-10 200 7-10 200 7-10	.# .# .4  
# 15 95 45 45 45 45 45 45 45 45 45 45 45 45 45	130-1 55 55 55 55 55 55 55 55 55 55 55 55 55	187 198 187 198 185 195 187 195 187 195 187 195 187 195 187 298 185 298	, 106 , 44 , 45 , 46 , 47 , 48 , 44 , 44 , 44	15 15 15 15 15 15 15	195 195 197 295 190,295 190,295 190 295 190 295 195 297 195 297	.9 .9 .4 .4 .4 .4	\$5 \$5 \$5 \$5 \$5 \$5	124-503 500-503 10-503 10-503 500-503	.% .4 .* .* .*
0 15 15 15 40 40 40 40 40 40 40 40 40 40 40 40 40	55 ; 55 ; 55 ; 55 ; 55 ; 55 ; 55 ; 55	181 198 185-195 (47) 195 (47) 195 (47) 195 (47) 195 (47) 195 (45) 294 (45) 294	, 106 , 44 , 45 , 46 , 47 , 48 , 44 , 44 , 44	15 15 15 15 15 15 15	195 195 197 295 190,295 190,295 190 295 190 295 195 297 195 297	.9 .9 .4 .4 .4 .4	\$5 \$5 \$5 \$5 \$5 \$5	124-503 500-503 10-503 10-503 500-503	. (8) . 4, . 7 . 7
15 10 41 40 40 45 10 25 80 85	55 ; 55 ; 55 ; 55 ; 55 ; 55 ; 55 ; 55	185-195 (87-195 187-195 187-195 187-195 187-195 187-196 185-296	.18 .18 .18 .18 .19 .14 .41 .41	15 55 35 35 35 35 24 25 25	144 514 142 504 302 152 42 144 534 346 544 340 544	.9 .5 .5 .5 .5 .4 	55 15 55 55 55	135-503 303-503 10-503 13-503 13-503	,4,
10 40 50511337621105: 40 41 19 21 80 81	\$5   1   5   5   5   5   5   5   5   5	(47.19) (47.19) (47.19) (47.19) (47.19) (47.19) (45.294	.40 .48 .49 EI TO PAIS ( .44 .44 .44	55 55 55 55 55 25	191 211 195 207 196 207 197 207 298 208 298 208	.5 .4 .5 .5 .5 .4 3	\$5 \$5 \$5 \$5 \$6	1.05.503 300.503 10.503 10.503	
45 49 5052,19 # (Cartille: 40 45 19 75 89 85	15 1 11   2	187 - 193 187 - 193 187 - 193 187 - 193 185 - 298 185 - 298	.44 .44 .44 .44	55 55 55 223 7638. 55	120 514 120 524 <del>201 701 10</del> 120 520 320 520	.4 .4 .4 	55 55 56 - 51	1.25.203 303.203 10.203	-
40 40 45 19 19 19 19 10 81	55   56   55   55   55   55   56   57   58   58	187 - 193 187 - 193 187 - 193 185 - 298 185 - 298	.44 .44 .44 .44	55 <b>(21)</b> 1238, 54	124 514 124 324 <del>224 122 42</del> 124 524	.4 .4 	44 44 4		•
50 45 70 25 80 85	55 ( 55 ) 55 ) 56 )	187 172 185 756 185 756	.49 .44 .44 .44	54 54 •	124 514 124 524 Wed 162 4E	# 5700 Bis .4	1. 1. 1. 1. 1.	:4201	•
50 45 70 25 80 85	55 ( 55 ) 55 ) 56 )	187 172 185 756 185 756	.44 .44 .44	\$4 •	1M 311	-4	• • •	•	•
65 75 75 80 85 70		ist 794 ist 794 ist 724	.44 .44 2.9	25	12 312 •	1,7	- 51	•	•
19 25 80 85 90			.44 3.8					141 116	
80 85 30	11		3.9	w	194 211				
85 30	11						-	-	-
70	•	FER 334		-	•	-	<b>3.</b> T	:%: 7 <del>01</del>	.•
FCS EC; 13-773		-	1.1	•	•	-	• \$3	136 713	.7
F D; 13-73		LESE 587 1	E	34:	erine eri	7	14:		
	KIE IN	o kite u	MATTER						
		obj. T of	.=	14	141 740		35	:4) 1'3	,4
	_	) 14 TH		14	int las	<b>→</b> 等	15	· · · · · · · · · · · · · · · · · · ·	_6.
		44.75°  45.730	.≇ _⊈	44 44	314 33A	_∓ _≇	11 14	191 T#1 197 T#1	,4. ,4.
saus émo un	-				210 34		**	1 1	
		140 Jan	.*	15	3:10- 3:as		15	** 143	.4
		jan jan	-8	55	3-79. 2-m	_#	44	144 145	.*
		) 15-3-10   1001 3-10	_# _#	44 44	14, 144 340 340	_≉ _≇	14 15	14.14	.4
Sint does an	-			* #	· · · · ·	-=	23	<b>14</b> (14)	_4
M FA	<u>#*!</u>	Haring 14	<u> </u>	-	-237 112 11	-3-3-	1	-Menus 4	==
	_	10 t 743	.4	10	:-1. 134	.4	35	144 145	.*
-		ren. Teki	.4	44	114 (4)	.*	44	198 598	.4
		145 Jab 146 Jab	. <del>4.</del>	15 14	(10), (20)	_=	<b>55</b>	194 197 244 197	.=
		145 343 140 344	. *	13 14	194 341 194 341	.\$ .&	55 25	Sad Same	. % . %
		<u> </u>	I a pr	ara prop.	er er er	n sio ei	•		
		**2 275	-*	4.5	- <b>% 3</b> 91	.=	55	196.199	•
	27 ;	. <del>1</del> 1-24	. 9	- 179	152 391	- #	42	14) 355	. 1
74	-	•	-	•	•	-	•		- <del>-</del>
	4" (	ers Too	@	12	144.714	ā <b>.</b> 🖨	<u>4.2</u>		
		. 45 710		•	:+1.2:3	•	•44	110 231	•
			el the paint				····	<del></del> -	

	-	TEACH SET	·		- 12	·		TASED SET	1
£1- <b>÷</b> ≥<	en i		7:Mat:	6:1	On 1 Temp	grates rés	Gat	Oal Temp	
Turk National : )	*P*+\$	is/Sut •*D	Trace <sup>1</sup>	Pr <del>esser</del> i Pres	(13) Io <sup>rga</sup> te	Trees.	(†31)	io.7011 (**)	Tisce ical
elm. Y		en ×III u	DPI-ZTPS						
76	***	ime in	-1	55	170-144	£	55	14, 17,	. 🛊
***	*	176 175 176-175	E	4.4	147.349	.=	55	197 (191	_#-
29 29	•••	134 134 144	.4 .4	1.3	}*** 175 271 001	.*	% 4:	340 145 340 145	.ē
عمزه الاعباد	a white same								
>- -		iya iva	. <b>E</b>	7.5.	3-33- 1 <b>-4</b> 5	. 3	` <b>t</b> ş	300 700	. \$F
£ *#	*14 *14	ንም. ንሳ. ንም. ንሳ.	-4 -4	54.	141 141 141 141	.≛ .≑	<b>4</b> 3	197 197 197,7197	_集 _集
4.5	1.2	J-v- 3-v4	_ Z	11	INC.	_ <del>=</del>	4.	740 745	. 9
THE OW	and the sact	parr #							
(-15 35):		<u> </u>		141	- <b>PERES</b>		5	- Weight L	<b>12</b>
1	77	J-91-7-1	.4	14	174 TV	_=	*2	170.7145	.5
2.7	19	157 2-3	_5	55	175 175	_4	***	1-1 (-)	.4
<u> </u>	37	177 255		<b>5</b> 5	847 July	_5	55	194 299	-*-
41 40	37 44	197 Just 197 Just	_% _%	15 15	14, 341 14, 341		<b>!!</b> :1	[+1 <b>7</b> 44 [+1 <b>7</b> 41	.*
_					•				
							=		
43 45	**	;** 3-14	~ <u>*</u>	4.3	140 July	_==	53	:95 73)	
畴	4.3	[% 2!r	_ 4	1.4	14 38r	_4	5.	274 214	-⊕
7%	<b>-</b> .	•	•	•	më eë test		• •	od et lest	
#2 <b>2</b> *₹	4.)	-192,329 	3 _ &				¥		
12	•	ಣಚಿತ್ 1+ಡ1							
		260 II (			1 <b>125</b> 325 1			4500 HT 4	
	<u>-1534155  </u>	SED WITH L	PHATE C		-	-			
•	77	146 145	.4	- 4I	}\$\$\$ 1#\$		74	12. [4]	.4
1/6	<b>#</b>	195 7285	. <del>.</del> .	4.5	340 140	_=	11	ind and	-4
27) 163	%# \$\$	] [15] [15] [15] [15]	,4. ,4	14 14	364 376 187 376	_# _\$	• • • • • • • • • • • • • • • • • • •	(M) (M)	_4 _4
					•	••			
13	11	(m) (14)	J <b>4</b>	7.5	197 193	_≇	42	*** ***	
<del>\$</del> \$	11	172-770	_4 <u>6</u>	11	144 742	_&_	44	195 195	.4.
v 43	11 15	[報 ] 物	.÷ .*	75 7-2	1年 7官 1年 7官	_\$- _®	44 44	197 198 44 147	.4
	३३ भी नेतर्स स्तर्वह		_ <del></del>	79	e-4 15e	_==	77	Acres 4 me	^ <del>=</del>
and No.	<b>=</b>	-mean	<b>112</b>	<u> 71</u>	Labert 14		24	-11347== 3	
3	11	ing [ and	_4	42	HA MA	_ <b>4</b>	*5	ind in	.4
15	14	192. T93	.5	<b>€</b> E	191 198	_\$	75	13 TT	.4
<del>#1</del>	55	194 (15)	_=	<b>%</b> =	Catal C+1	- <del>4</del>	45	191 <b>7</b> 53	-4
27,	53 55	14年11年	÷. _÷.	<b>74</b> 11	See See	.\$ 4	44 47	"私"字符 : 9人子符	
**		int im			_				, <del>-</del>
						# ### <u>#</u>			
14	15	141 145	_4.	₹.	3-82 195	_4	\$-E	of the	. 4
44		•	-	• •3	(A) 7+2	. <u>*</u>	*	tar Tra	.9
*4	• ••	*4* * 1	*	-		-	•	* - = = = = =	•
40		•	=	چه	12 h 2 m2	.4	<b>⊕</b> t	144 754	
<b>u</b> 5	•			*	•	-	•	•	-
<b>100</b>	44	tak 11-	- 2	17	544 74 s	. <b>=</b>	40	144 3 69	.*

TAM TIL	. 1394ETS	o mente entre personales.	
1-equil	Tibe state		-
- 7557	7.47		
intentes;	الحية	Commercia	
territor See	1		
•	-	S da	
the star fee.	2		SECURE OF SECURE OF SECURE SEC
4	5		- 1
2.4		- Para from test stand	1
2.4	-4	to were in trace	1
3.4	.4 .	In with 15 trace	i
4.2		. Note time: intremed sing . Simposts were time:	
		tiver patch rate	Ī
7.4			Ī
14.* 11.#	1.4	-	I
12.5	1.3	•	
	ANTH AT LINE	Shaft down.	- 5
Antology for )	_		3
5.5	1.4		
1-2	-1	<u>-</u>	⊕ II Brombel   d 2 - Mille   Bill-brown ( av.) - derskebbler (ij)
J.	.*	•	ž
<b>1</b> .			ā
₹ ♦	1.4	•	
3,	.4	•	ł
14.	.† .8	*	Ŧ
1 F.		-	į
<b>\$4.</b>			ž
is.		•	Ī
17 <u>.</u> - 19 <u>.</u>	-*	-	ŧ
F9.		•	
<b>.</b>	.*	*	3
. <u> </u>			C Destrict Strate of the Strat
į.			ě
3-1 4-35	*	•	-
* 11	1.1	-	-
E •	1.1	•	-
: 15-44 15-44		-	
27-25	5 #	de	-
Ja-ja	•	* -	•
	1 2	•	:
-	-	*	-
fining bury See 5			-
			~
9— 2 2 • ·	<b>i</b>	•	÷
#-1:	4		
	: 7	_	
_%- <del>5-0</del>	•		
.≓ 29 - 25	5		*
terior de s			-
<b>⇒</b> ;	4	_	-
2- <sub>-</sub> 2	•		
	.\$	-	
<b>;</b> ;;	×.		
. 79 m	-	=	*
<del></del>	-	•	ŝ
Trimbal on Late probets to gover a trop materia	افته دروسور. محمد فمسورة	t esta, retiring to see magazine estate Society 6.9 mag year	1

7812 V.	::. T2832 22372	ME AND THE EXCHANGES	
Elagned	Tibrat pag		
Tibe	Trace	-	
(Eller)	_ tol	Comments	
1353 Sec 1			
.1.	-3	-	
1.7	.4	-	i
¥.2	-3.	·· hia and	
*.4	-4	•	
13-3 14-9		Sawtouch signature	
17.8	-  -  -  -  -  -  -  -  -  -  -  -  -	FitO change	
18.4	.# -	- Section's suprature	
18.2 29.6		Frich change	į
3.4	1.4	· <u>·</u>	4
3509 Sec 2			
1.6	-5		-
1.s 1.s	-3	Ī.	-
3.4	-3 -	- 71tc. charge	
7.1 11.6		•	1
12.4		<u> </u>	1
\$4.6	.4	- fates change	I
85.#	1.3	· · · · · · · · · · · · · · · · · · ·	7
14_8 17_8	[1] - ·	- Paten ename	į.
19.2	1.2 1.4 2.8	End of test	;
#### ##LJ			THE CHART HE PARKS AND AND THE PARKS AND THE
1.4	_		
1.#	-1 .7	•	·
4_≑		-	ŧ
7_8 80_4	.3	-	:
29.4	.*		•
\$4.4		· fivo <del>case</del>	*
17.6	1.7	- Service sayatay	
	ind of test		•
			•
<b>≣</b> ₽	-2	•	
9	.# .4	*	•
=	.3	-	
1-14 13-21	_+	•	
* 9 9 8	. *	•	
± =	1.4	•	
<i>3</i> 76	E_2	-	
.25 .25~ pp	1-1	•	
	1.2	•	
1800) (tr )			
8 Z 2-4	3.	-	-
#-* *_#	. 3	. Itself comm	
an 14: 15		Antonia Compa	-
48 2 29.8	•	***************************************	
··	z.	-	
significant -			
9-12	. 9	-	
; 4 ; 4 ; 4-14			
-29 		terpers series	
2% 2% 2%		7:1-7 *1	
24	a#		
98 -	•.	•	
Tableton de pad To-pus collegetor	la tueve te Medical as	od obel votenijo teano postatoj Pistošo - Sasče, diš mais per	

	n Bot 6	Response	ž	ş.	Ş.	S.	<b>5</b> 2	0%	0% 0%	Partial	Partial	**	***	# 0 7-			*
	Bangline Set 6	- 0 = 1 L	\$115113	6.101.20	\$116125	\$116130	*116134	5116140	\$116145	5117100	\$117110	5117115	5117120	4117125			
	* 1 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Montonec	20	No	ž	SE SE	<b>%</b>	No.	22	No.	ž	5.55		****	No	Yes	* A.A.
MOCHEOM CHAYON THRENATURE OF BARCINE TEST GEARS OF MORLUBNICATION TESTING	Hanelline Bel. 5	ひズ ラミート	05-150-21	12104100	12 10% 10%	01150151	12,04,20	06150151	12105140	35150120	12 (05 155	17 (00) 10	12 (04) 15	12 (46) 25	12.06.15	12.106.150	12107100
	The second secon	6 (40 K) 6	26.0		%c	ž	3E	3 7.	Z.	5 ·	Partial	38.	Year	Yes			A KERNEN HAMMA (WASHING MANAGAMA)
						,			•		,				3	ke keelende op begreen het gebeuret en die geb	
	A de la company de la comp		2	No	32	200	Slea Slea	es 75.	4	<b>3</b> .	Partial	2	You	Year		ā	() () ()
	# 5		1,41,150 11	1141155 1	N COLOTIC	8 11:1P	S + 27 - 27 - 1	E 00.2411	1142148 3	1 142130 P	11111	*	¥ 241.054			PATTIKENGHA-IDHIBITIK - DISMATTIKENGHANAKA	
	The state of the s					Farttal											Herritador Handelle Villelik in die in de
TABLE 1X.	The A. O.		ex ett.(12)	12:13:15:8 Ha	Marinita No	rd (flact)	A SEIDELES	医骨骨 医骨骨骨骨骨髓	TOTAL STREET	wax getreter		,	•	•		 	nedisantelianikak 8 allikebisinifodilis
шино-сий кевини на ний капитали шино-сий кевини на ний капитали	Alle Control C	4 7 2 4	3	2	2	-	## #7	** **	2	<u>;-</u>							Residentia de Principalis de Princip
	n menthesinteennemennementeennementeennementeennementeennementeennementeennementeenn	5-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	to the entry														nReidthaugh de <sup>1. vo</sup> ánnsutgagith
	を			<u>.</u>		che	ē,		ą c	- -	·	;	í.	÷		ž.	odenoskilete k dis-kor kaltimodeniliodenilimiseliiniliseliiniliodeni na

to department of the same of t	annentations declarations and the second	· emercent depropressions in	тавье х.	THERMOCKR AT CCNCLU	ON JAYON SION OF NO!	THERMOCHRON JANYON TEMPERATURES OF 1 5.	S OF A STR	OF v.S"7-A2 TEST GEARS TESTI G	ıns			
Trestroct ca	Name o designation with the season of the se	nandong train delenantement delenatement	r general ser semenatural y managementation	Andreas Communication of the C								
Cray :: Temperature	VASCO Set	O Set 3 Respense	VASC: Set 2	Set 2 kesponse	VASCO Set	Set 3	TIMG F	VASCO Set 4 me Response	VASCO Sot 5	Sot 5 Response	VASCC Time	VASCC Set b me Response
1240	11:50:07	37.	12:23:40	No	12:38:15	c.X	3:57:00	ΝĢ	6:18:55	o <sub>N</sub>	6:27:55	%;
1550	:1:58:15	Ç,	12:24:00	Š	12:38:20	Ñ	3:57:05	ON	4:19:05	Š	6:28:00	Š.
935	11:58:30	o S	124:10	St.	12:38:25	Partial	1157110	No	6:19:10	Š	6:28:05	o S
940	11:58:40	No.	12:24:29	ž	12:38:30	Yor	3:57:13	Partial	6:14:18	c <sub>N</sub>	6:24:13	δ. 20
7.88	11:58:45	Yes	12:24:30	No	12:30:50	Yes	3:57:20	× 6 ×	42 6119	c N	6128115	 
510	11.58155	%	12:24.0	No No	12:12:45	Yec	3:57:30	Yes	6:19:35	o N	6:26:20	5.43
64.2	11:59.50	Yes	.2:24:50	* >·	12:38:50	Yes	3:57:35	Sαλ	6119145	o. O	6:29:25	Yes
519	11:59:20	Yes	12:25:00	Partial	1	,	3:57:40	51 24	6:19:55	c N	6:28:30	Yes
55	•	•	12:25:20	Yes	1	1	3:57:45	Yes	6:20:03	oN O	6:28:35	80.51
240	:	·	12:25:39	Yes	•	٠		•	6:20:10	Ç Z	ı	
430			ı	÷	1	•		•	6120:22	Yes		ı
390	ı	•		•	1			•	3120136	Yor	ı	:
350	,	•	•		1	1	ı	t	6:20:45	Yes		,
300		ı		ı	•	·	•	,	ı		1	i
250			1				•	1			:	

TABLE	XI. OBSERVE	D DATA FROM	NONLUBRICATION	TESTING
Set	Load (percent)	Duration (minutes)	Pinion-Blank Temperatures (°F)	Torque Loss (percent)
Baseline T	<u>est Gears</u>			
1 2 3 4 5 6 VASCO-X2 T	100 100 85 85 75 75	25.0 13.5 30.0 30.0 30.0 30.0	650 to 1000 788 to 840 430 to 570 430 to 570 250 to 300 540 to 570	44.5 21.0 13.0 30.0 4.0 6.0
1 2 3 4 5 6	100 100 85 85 75 75	25.0 19.0 17.0 30.0 30.0 30.0	660 to 770 570 to 660 840 to 930 788 to 844 390 to 430 710 to 788	38.0 27.0 29.0 21.0 4.0 22.0

deposited in the fillet root in the form of a metal fin on practically every tooth of the pinion member. The gear member was also heavily scored, but to a somewhat lesser degree than the pinion, with heavy wear indications at the toe end of the driven side. A great deal of metal debris was found in the test housing. This debris was in the form of slivers and splinters. The connecting cross-shaft to the slave beyel gearbox developed heat color stains of 'ight blue, violet, brown, and amber, in that order, coming away from the test gear mesh. Heat stains of comparable colors on 4340 steel (the shaft material) usually indicate a temperature of 650°F to 750°F.

Disassembly of the test pinion was difficult due to ovality of the mounting holes. In addition, several areas indicated the initial stage of welding the bolts to the mounting holes.


# BASELINE GEAR SET 1



Pinion Number Al02




Gear Number Al02



Pinion Number A103







Gear Number Al03

Figure 16. Final Condition of Baseline Test Gears (AISI 9310 Steel) After Nonlubrication Testing (Sheet 1 of 2).



Number Al03





Pinion Number Al05




mber Al03



Gear Number Al05



BASELINE GEAR SET 4




Pinion Number Al06



Gear Number Alu6

Figure 16 - Continued (Sheet 2 of 2).



BASELINE GEA



Pinion Number



Gear Number

# SELINE GEAR SET 5



ion Number Al07



ar Number Al07

# BASELINE GEAR SET 6



Pinion Number Al08



Gear Number A103



VASCO-N2 GEAR SET 1



Pinion Number Alli



Gear Number All2

Pigure II. Final Condition of Wascowil steel Tears agree Monlucrication Tearing Sheet 1 of 1 .

Preceding page brank 4-


NOTE: SEAR SET NO. I IS SHOWN ON SHEET I IN THIS FIGURE. VASCO-X2 GEAR SET 3



Pinion Number Al06



r NO. 2 EET 2



Gear Number A107




VASCO-X2 GEAR SET



Pinion Number Al04



Pinion Number Al



Gear Number Al06

Figure 17 - Continued (Sheet 2 of 3).

Preceding page blank


51



CC-X2 GEAR SET 2



nion Number Al04






Pinion Number Al04




Gear Number Al06




VASCO-X2 GEAR SET 4






Pinion Number Al09




Finion Number All




Gear Number Alog



Gear Auster Allo







ASCO-X2 GEAR SET 5

WASCO-X2 GEAR SET 6




inion Number Allo



ear Number All0



Pinion Number All2



Gear Number All3



The evidence of metal flow on the pinion gear teeth is a good indication that the temperature experienced by the pinion blank was in excess of 1000°F. The temperature gages were missing from the pinion and found in the test housing. All of the temperature dots on the sensor plates had turned black.

In view of the extensive damage sustained during this test run, it may be said that this test could have been curtailed earlier. However, since there was no previous experience with testing conducted in this environment, it was mandatory to continue the test run long enough to sustain a reasonable degree of damage.

Baseline Gear Set Number 2 - Inspection of the temperature gages after run-in testing revealed that the low-temperature (230°F, 240°F, 250°F, 200°F) dots were exposed. In addition, one high-temperature (350°F) dot was exposed, but this was believed to be the result of a breakdown in the protective coating. Visual inspection of the tooth surfaces at the end of monlubrication testing revealed severe scoring and metal flow, heat discoloration, and destructive pitting on the drive side of the pinion member. Heavy scoring was evident on the driven side of the mating gear member, along with a lesser degree of pitting. Contact patterns were visible on the coast side of both members, indicating contact on both sides of the teeth, which would present evidence that the installation backlash was taken up in thermal expansion. Finion blank temperature checks were made within minutes of shucdown. These checks indicated that the pinion-blank temperature was between 788°F and 840°F. This would indicate a softening of the carburized case, since AISI 9310 steel has a tempering temperature of approximately 350°P.

Baseline Gear Set Number 3 - Visual inspection of the tooth surfaces at the end of nonlubrication testing revealed heavy scoring in the addendum and dedendum of the pinion member, with pitting at the pitchline. Scoring and pitchline pitting were evident on the mating gear member, but to a considerably lesser degree. Contact patterns were visible on the coast side of both members; however, they were much lighter and covered less area than the patterns resulting from the 100-percent load level testing.

<u>Baseline Gear Set Number 4</u> - Visual inspection of the tooth surfaces of both members at the end of nonlubrication testing revealed conditions very similar to the third baseline test set.

Baseline Gear Set Number 5 - Visual inspection of the tooth surfaces at the end of nonlubrication testing revealed moderate to heavy scoring, and moderate pitting at the pitchline of the pinion member. The same condition prevailed on the tooth surfaces of the gear member, but with less severity. The pinion blank temperature checks indicated a blank temperature between 250°F and 300°F, and the 230°F temperature dot was exposed as well.

Baseline Gear Set Number 6 - Visual inspection of the tooth surfaces of both members at the end of nonlubrication testing revealed conditions very similar to the fifth baseline test set.

VASCO-X2 Gear Set Number 1 - After the first 50-percent load run-in, inspection of the temperature plate gages indicated that all of the lower temperature and three of the higher temperature dots were exposed. This exposure was believed to be the result of failure of the protective coating and exposure to the lubricating oil.

Visual inspection of the gear tooth surfaces at the end of non-lubrication testing revealed heavy scoring and pitting on the driven side of the pinion member. Scoring and pitting were evident on the driven side of the mating gear member; however, the damage was not as severe when compared to the pinion member. There was no visible evidence of cracks on either member. Contact patterns were visible on the coast side of both members, indicating that the installation backlash was insufficient to counteract thermal expansion during the non-lubrication testing.

VASCO-X2 Gear Set Number 2 - Visual inspection of the gear tooth surfaces at the end of nonlubrication testing revealed severe scoring and heavy pitting at the pitchline of the pinion member. In addition, metal debris was deposited on the coast side, particularly near the heel end. The gear member displayed scoring and pitting similar to the pinion, but with less severity. There was no visible evidence of cracks on either member. Contact patterns were visible on the coast side of both members, indicating that the installation backlash was insufficient to counteract thermal expansion during the non-lubrication testing.

<u>VASCO-X2 Gear Set Number 3</u> - Visual inspection of the gear tooth surfaces at the end of nonlubrication testing revealed severe

scoring and heavy pitting at the pitchline of the pinion member. In addition, metal debris was deposited along the tooth surfaces. The gear member displayed scoring and pitting similar to the pinion, but with less severity; the tooth surface of the gear member and the topland were rough with metal that had been deposited in these areas. There was no visible evidence of cracks on either member. Contact patterns were visible on the coast side of both members, indicating that the installation backlash was insufficient to counteract thermal expansion during the nonlubrication testing.

<u>VASCO-X2</u> Gear Set Number 4 - Visual inspection of the gear tooth surfaces at the end of nonlubrication testing revealed heavy scoring and moderate pitchline pitting of the pinion member. The gear member displayed scoring and pitting similar to the pinion, but with less severity. Contact patterns were visible on the coast side of both members, however they were much lighter and covered less area than any of the previous tests. There was no visible evidence of cracks on either member.

<u>VASCO-X2 Gear Set Number 5</u> - Visual inspection of the gear tooth surfaces at the end of nonlubrication testing revealed moderate scoring and pitchline pitting of the pinion member. The gear rember displayed similar conditions, but with less severity. There was no visible evidence of cracks on either member.

<u>VASCO-X2 Gear Set Number 6</u> - Visual inspection of the gear tooth surfaces at the end of nonlubrication testing revealed heavy scoring and moderate pitchline pitting of the pinion member. The gear member displayed similar conditions, but with less severity. There was no visible evidence of cracks on either member.

# METALLURGICAL E ALUATION

A destructive metallurgical examination was performed on one baseline spiral bevel pinion (serial number AlO3) subjected to the 100-percent load level and run for 13.5 minutes, and on one VASCO-X2 steel spiral bevel pinion (serial number AlO1) subjected to the 100-percent load level and run for 23 minutes. The results of this investigation are shown in Figures 18 and 19.

Both test pineous displayed excessive wear on the drive side of the tooth profiles, resulting in a wearing away of most of the carburized layer. Plastic flow of metal from the drive

flank over the tip onto the coast side was apparent on both test pinions.

In general, the metallurgical examination revealed that both test pinions were subjected to extremely high temperatures. The VASCO-X2 pinion displayed streaks of radial rehardening, shown in Figures 20 and 21, on the drive flank of each tooth. A section taken through one of these localized streaks is shown in Figure 21. It is estimated that this area was subjected to a temperature in excess of 1700°F.

Table XII presents a comparison of hardness along the tooth profile of the two test pinions at the toe and heel positions at two locations 180° apart. This table reveals a higher hardness for the VASCO-X2 pinion along the entire tooth profile and in the tooth core. Figures 22 and 23 present metallographic profiles of the gear teeth. Figure 24 shows effective case dept. of selected positions.




Figure 18. Baseline Pinion Gear (A103) After 13.5 Minutes of Oil Starvation at 100-Percent Load.




Figure 19. VASCO-X2 Pinion Gear (A101) After 23 Minutes of Oil Starvation at 100-Percent Load.


Baseline (No rehardening characteristics exhibited)



VASCO-X2
(Rehardening characteristics exhibited on each tooth addendum)



Figure 20. Paseline and VASCO-X2 Pinion Gears (Al03 and 2101) After Nital-Etch Inspection.



Radial lehardening Streaks (11%)



Metallographic Section Through Rehardening Area; Maximum Depth, .601 Inch. (500x)



Pigure 21. Rehardening Characteristics Exhibited by VASCO-X2 Pinion Gear (AlO1) After Nital-Etch Inspection.

TABLE	XII. HARDNESS DETE	RMINATION					
Lccation	on Teeth	Rockwell "C" Baseline Pinion (A103)	Hardness VASCO-X2 Pinion (A101)				
0° Dia	meter						
Adjacent to surface	in carburized area		en de la companya de				
Drive flank -	toe position heel position	39 37	55 52				
Nondrive flank -	toe position heel position	4 7 44	58 54				
Root	toe position heel position	44 40	55 54				
Core of tooth - (approximately 0.1 inch from surface)		30-32 27-28	46 45-46				
180° Diameter							
Adjacent to surface	in carburized area						
Drive flank -	toe position heel position	<b>4</b> 2 39	40 38				
Nondrive flank -	toe position heel position	49 45	54 43				
Roet -	toe position heel position	48 44	52 46				
Core of tooth ~ (approximately 0.1 inch from surfame)	toe position heel position	33-36 30-31	45 35–38				




Figure 22. Metallographic Profile of Tooth From Baseline Pinion Gear (AlO3), Exhibiting Wear and Deformation of Drive Flank Carburized Case (9X).




Figure 23. Metallographic Profile of Tooth From VASCO-X2
Pinion Gear (AlO1), Exhibiting Wear and Deformation
of Drive Flank Carburized Case (JX).




Figure 24. Effective Case Depths and Hardness Traverse Data of Drive Flanks at the 180° Position.

#### **CONCLUSIONS**

- 1. The proposed method of measuring blank temperature by the use of gages during the noniubrication testing proved to be unsuccessful due to exposure of the gages to the lubricating oil and/or exposure to the excessively high temperatures. A substitute method employing thermal crayons was utilized as a backup. This method can only be used at the conclusion of the individual tests, and it is a judgement evaluation with regard to color change in a specified time interval. Therefore, the accuracy of this method is questionable as to the determination of the actual gear-blank temperature. However, these temperature determinations were used as index numbers for comparisons between tests.
- 2. Destructive metallurgical evaluation of both a 9310 steel pinion and ε VASCO-X2 steel pinion (after completion of the 100-percent load nonlubrication test) revealed considerable metal flow in both cases. This would conservatively indicate pinion-blank temperatures exceeding 1100°F. It is therefore concluded that gears fabricated from different compositions of steel, subjected to these temperature levels, will not provide significant improvements in non-lubricated operating time.
- 3. This test program utilized spiral bevel gears which were reground to restore the tooth surfaces. The regrind increased the installation backlash by approximately twice the design backlash. Results of the nonlubrication testing at the 85-percent and 100-percent load levels indicated that contact was made on both sides of the teeth. This was evidenced by the resulting coast patterns on both members (pinion and gear). This indicates that even with the increased backlash, there was insufficient clearance to accommodate thermal expansion during the nonlubrication testing. It can be concluded that standard backlash could have resulted in an early failure.
- 4. Both the VASCO-X2 steel spiral bevel gears and the AISI 9310 steel spiral bevel gears successfully completed non-lubrication testing for 30 minutes at the 75-percent load level. Visual examination of the gear tooth surfaces indicated light surface distress in both cases. This would indicate that the operating load level has a significant effect on gear performance in a nonlubricated environment. However, it should be noted that this test was conducted with increased backlash and in the moderate speed regime (pitchline velocity, 5360 feet per minute). Comparisons should be restricted to designs with comparable parameters.

5. Experimental gear testing usually results in significant data scatter, thereby requiring a sufficient number of test specimens to accomplish a statistical evaluation of the test results. This program consisted of a very small number of test specimens; consequently, the test results generated by this program should be evaluated with discretion.

#### RECOMMENDATIONS

Based on the resul's obtained from the experimental testing and from the evaluation performed in the execution of this program, it is recommended that further work be directed in the following areas:

- Conduct a destructive metallurgical examination of the VASCO-X2 steel spiral bevel gears and the AISI 9310 steel spiral bevel gears which survived the 75-percent load testing (nonlubrication), to establish a comparison of the effect of the reduced load on the two gear materials.
- 2. Conduct an experimental test program with AISI 9310 (AMS6265) and VASCO-X2 steel spiral bevel gears operating under conditions of minimum oil flow to sustain continued operation for at least 30 minutes. This proposed program would provide essential data for the design of emergency helicopter transmission lubrication systems, incorporating concepts such as the viscous pump.

# SELECTED BIBLIOGRAPHY

- 1. Martin, H. M., THE LUBRICATION OF GEAR TEETH, Engineering, Volume 102, 1916.
- 2. Blok, H., MEASUREMENT OF TEMPERATURE PLASHES ON GEAR TEETH UNDER EXTREME PRESSURE CONDITIONS, Proc. Gen. Disc. on Lubrication, 1937.
- 3. Blok, H., THEORETICAL STUDY OF TEMPERATURE RISE AT SUR-FACES OF ACTUAL CONTACT UNDER OILINESS LUBRICATING COM-DITIONS, Proc. Gen. Disc. on Lubrication, 1937.
- Institute of Petroleum Gear Lubrication Symposium, London, England, Pebruary 1952, <u>Journal Institute of Petroleum</u>, 1952.
- ASLE Gear Lubrication Symposium, Chicago, Illinois, January 1959, Lubrication Eng. and ASLE Trans., 1959.
- Institute of Petroleum Gear Lubrication Symposium, Brighton, England, October 1964.
- Almen, J. O., DIMENSIONAL VALUE OF LUBRICANTS IN GEAR DESIGN, SAE Journal, Volume 50, Number 9, Page 373, 1942.
- Kelley, B. W., and Lemanski, A. J., LUBRICATION OF INVO-LUTE GEARING, Proc. I. Mech. E., Volume 182, Pt. 3A, Pages 173-184, 1967-1968.
- Blok, H., SURFACE TEMPERATURES UNDER EXTREME PRESSURE CONDITIONS, Second World Pecroleum Congress, Paris Section 4, 1937.
- 10. Ibrahim, M., and Cazeron, A., OIL PILM THICKNESS AND THE MECHANISM OF SCUPPING IN GEAR TEETH, Lubrication and Wear Convention, 1963, Institute of Mechanical Engineers, London.
- 11. Askwith, T. C., Crouch, R. R., and Caseron, A., THE RELATIONSHIP OF LUBRICANTS AND ADDITIVES FOR OPTIMEN EFFECT AND A THEORY OF SCUFFING, Proc. Symposium on Gear Lubrication, Institute of Petroleum, 1966.

- Coleman, W., A SCORING FORMULA FOR BEVEL AND HYFOID GEAR TEETH, <u>Journal of Lubrication Technology</u>, ASME, Volume 89F, Page 114, 1967.
- Grupin, A. N., and Vinognadova, I. E., INVESTIGATION OF THE CONTACT OF MACHINE COMPONENTS, Book Number 36, Moscow 1949, DSIR, London, Translation Number 337.
- 14. Chen, H. S., CALCULATION OF ELASTOHYDRODYNAMIC FILM THICK-NESS IN HIGH SPEED FOLLING AND SLIDING CONTACT, MTI Report Number 67TR24.
- 15. Benedict, G. H., and Kelley, B. W., INSTANTANEOUS COEFFI-CIENTS OF GEAR TOOTH FRICTION, ASLE Transactions, Volume 4, Number 1, April 1961.
- 16. Leach, E. F., and Kelley, B. W., TEMPERATURE THE KEY OF LUBRICANT CAPACITY, ASLE Paper 64LC-13, 1964.
- 17. Blok, H., LUBRICATION AS A GEAR DESIGN FACTOR, Proceedings of the International Conference on Gearing, Institute of Mechanical Engineers, 1958.
- Kelley, B. W., A NEW LOOK AT THE SCORING PHENOMENA OF GEARS, SAE Transactions, Volume 61, 1953.
- Lemanski, A. J., GEAR SCORING DESIGN GUIDE FOR AEROSPACE SPUR AND HELICAL POWER GEARS, American Gear Manufacturers Association Information Sheet 217.01, October 1965.
- 20. Dudley, D. W., PRACTICAL GEAR DESIGN, McGraw Hill Book Company, Inc., New York, 1954.
- 21. Bodensieck, E. J., SPECIFIC FILM THICKNESS AN INDEX OF GEAR TOOTH SURIACE DETERIORATION, AGMA Technical Division Meeting, 1965.